



Models usage instructions

- We suggest to use OrCAD v. 16.6 Hotfix-s032 to avoid convergence problems and speed up the simulation.



- Before starting the simulation make sure that the option “Initialize all flip-flops” is set to “0”.



- In case of convergence problems check the option “AutoConverge”.

